

# Newaygo Series I Construction Progress



### Project Duration is <u>30%</u> Complete



HS Gymnasium Painting



Football Field Track Subbase



Football Field Fencing and Maintenance Strip

### WORK IN PROGRESS

### This Month

- Football Stadium Renovations
  - Completed track demolition, underdrain, and new sub base
  - Completed underground utilities around track.
  - New fence posts and maintenance strip ongoing
- High School Renovations
  - Roof replacements ongoing
  - Completed HS gymnasium bleacher floor demo
  - Compplete painting of HS gymnasium walls
  - Begin wood gymnasium floor
  - Miscellaneous site wide exterior improvements ongoing including sidewalk, sanitary, and asphalt repairs
- Middle School Renovations
  - Replacement fire alarm, roofing, and exhaust fans in progress

### Next Month

- Football Stadium Renovations
  - Asphalt paving around new track
  - Continue entry plaza concrete and foundations.
  - Continue fencing around track
- High School Renovations
  - Continue roof replacements
  - o Gymnasium floor installation ongoing
  - Miscellaneous site wide exterior improvements ongoing including sidewalk, sanitary, and asphalt repairs
- Middle School Renovations
  - Replacement fire alarm, roofing, and exhaust fans in progress





# Newaygo Series I Construction Progress



### PROJECT MANAGEMENT UPDATE

### Safety

 This month's Safety Goal focuses on Heat Stress and the importance of staying hydrated and monitoring the weather to perform work.

## Schedule

The project is on schedule

# **Other Progress**

Series 2 High School Renovation design in progress



Football Entry Plaza Underground Utilities



High School Wood Gym Floor Materal



High School Underground Utility Installation



High School Gymnasium

